


Quick Start Guide – ORP1000 Oxygen Reduction Potential Sensor


Procedures for connecting and configuring the Greenspan ORP1000 Sensor.

You should have received:

- Certificate of Conformance Sheet
- Software CD
- Greenspan ORP1000 Sensor
- Cable Options per order



Sensor may be fitted with optional removable cable



The ORP1000 provides ORP measurement as a calibrated 4-20mA output over the full scale range of the sensor. Sensor requires a nominal 12V DC power supply, but will operate from 10-14V DC.

ORP1000 Quick Start Guide